

Error in JUMA TRX2 firmware 2008-02-08

Symptoms: CW shift changes to random frequency.

Applies to the JUMA TRX2 with SW versions 1.00 and 1.01

The changes

- Upgrade firmware version to 1.02. See the Boot Loader and programming instructions in the JUMA TRX2 page www.nikkemedia.fi/juma

Related information: CW shift value corrupts if VFO select is Split and the TRX2 is controlled via RS232 port with Yaseu CAT protocol. Fault disappears with a reset to the factory defaults. Before executing the reset to factory defaults write down your TRX2 calibration constants if they have been altered from the original values

Firmware availability: Software version 1.02 will be published in JUMA-TRX2 pages.

Virhe JUMA TRX2 ohjelmassa 2008-02-08

Oireet: CW shift muuttuu sattumanvaraiseksi luvuksi.

Virhe koskee JUMA TRX2 ohjelmaversioita 1.00 ja 1.01.

Muutokset

- Päivitä ohjelmisto versioon 1.02. Katso ohjeet "Boot Loader and programming instructions" JUMA TRX2 sivuilta www.nikkemedia.fi/juma

Lisätietoja: CW shift vakio korruptoituu, jos VFO valinta on Split ja TRX2:sta ohjataan Yaesu CAT protokollalla RS232-portin kautta. Vika poistuu, kun TRX2 laite palautetaan "tehdasasetuksiin". Ennen palautusta kirjoita kalibrointivakiot muistiin, mikäli niitä on säädetty.

Ohjelmiston saatavuus: Ohjelmistoversio 1.02 julkaistaan JUMA-TRX2 sivuilla